

Update on Two-Way Development

Presented by
Microcom Design, Inc.
May 2020





Two-Way Update – Over-the-Air Summary

- Project consisted of three major tasks:
 - Verify operation of the Two-Way Modulator installed at WCDA.
 - Measure the BER of the Two-Way signal at the allowed PSD.
 - Demonstrate the ability to synchronize and advantages of synchronizing transmitted Two-Way signal to UTC at the satellite.
- Modulator install completed November 22ND 2019.
- Two-Way Over-the-Air BER testing - on hold.
- Hop synchronization can be manually adjusted, but will ultimately need automatic alignment and tracking.
- Reliably receiving data at expected SNR at the correct PSD.
- Received signal level is in agreement with the calculated link margin analysis.

Two-Way Update – Modulator Install


- Installation was successfully completed in one day and the Two-Way Modulator was allowed to provide the DCPC (aka Two-Way) uplink signal for GOES-East.






Two-Way Update – Modulator Install

- Microcom has been able to reliably connect to the Two-Way Modulator installed at WCDA using remote desktop.
 - When not testing the modulator is configured to not hop and make carrier at 72.8 MHz, which correlates to a 468.8 MHz downlink signal.




Two-Way Update – Modulator Updates

- The following features were added to the modulator PC program which were necessary for testing:
 - Power level adjustment
 - Channel adjustment
 - 10MHz OCXO lock algorithm
 - Modulation modes
 - Remote programming
 - Hop timing delay adjustment



Two-Way Update – Modulator Updates


- Hop timing can be adjusted while hopping.
 - Allows for fine adjustments to facilitate hop alignment.
 - The monitor reports the current advance/delay amount.






Two-Way Update – Modulator Install

- Screen capture is using a 468 MHz cross Yagi receive antenna pointed at GOES East. The Two-Way Modulator is making the carrier for GOES-East and a signal generator is making the DCPC signal for GOES-West.



Two-Way Update – Link Overview

- Modulator needs to advance by 125 ms so the hop will reach the satellite on time
- Demodulator needs to delay by 125 ms so the locally generated hopping mix down signal and received hopping signals will align.




An aerial photograph of a satellite ground station facility. The site is located in a grassy area with a dense forest in the background. Numerous large parabolic satellite antennas are scattered across the site, some pointing towards the sky. There are several buildings, including a large central structure and smaller utility buildings. A paved road or runway is visible on the right side of the image. The text "WCDA" is overlaid in the center of the image.

WCDA




Two-Way Update – Channel Overview

□ LMRs are the primary users of this frequency band



Two-Way Update – Channel Overview

- The Two-Way signal hop in the interstitial frequencies





Two-Way Update – BER Measurements

- BER measurement task was delayed and is on hold due to unforeseen complications.
 - Strong interfering emitter
 - RF front end was damaged by an LMR transmitter.
 - February 19th to March 4th GOES operations were moved from WCDA to CBU.
 - This move caused significant project delays due to the DCPC signal being uplinked from the CBU instead of WCDA.
 - Two-Way Modulator installed at WCDA not at CBU.
 - This could be resolved by installing a second Two-Way Modulator at CBU allowing full fidelity during any subsequent switchover.
 - Adjustable power level from GOES
 - DCPC transponder on GOES is using AGC.
 - The AGC feature is thwarting attempts to lower the output power of the Two-Way signal needed to perform BER measurements.
 - Satellite movement
 - Minor satellite movement causing major hop timing misalignments


Two-Way Update – Interfering Emitter

- LMR signal +65 dB stronger than Two-Way
- 4 MHz away
- Damaged RF front end amplification stage




Two-Way Update – Interfering Emitter

- The RF front end was hardened against strong interfering emitters.
- RF front end is shown here successfully mixing the Two-Way 468.8 MHz signal to 455 kHz where it can be digitized and demodulated.




Two-Way Update – Interfering Emitter

- Shown here is the Two-Way Modulator successfully making 200 bps signal with RF front end down converting to 455 kHz.
- Microcom is reliably receiving over-the-air data with hopping at an SNR of 25 dB.



Two-Way Update – BER Measurements

- The signal level needs to be brought down closer to the existing noise floor to ensure BER through the GOES agree with the measurements taken during bench testing.
- Bench test screen shot at a BER $1.6e^{-4}$ with a SNR of 9 dB.





Two-Way Update – Power Level

- On March 6th the inability to adjust the power level coming from the satellite was discovered.
- Down Link Power Level Solution
 - Two options have been discussed:
 - Add a secondary carrier which would keep the AGC active while testing the Two-Way signal.
 - Place the satellite in fixed gain mode.
 - Both potential solutions were thwarted by the ongoing pandemic.
 - WCDA personnel were restricted to working on only critical operations which excluded a secondary carrier from being uplinked.
 - NSOF personnel would be needed to turn off the AGC but were also restricted from working on non-critical operations.
 - Either solution will allow for accurate and repeatable BER measurements.




Two-Way Update – Satellite Movement

- Satellite movement issue was found and research began on determining the impacts to the system on March 6th.
- Small satellite movements impacts BER measurements.
 - Two-Way hopping requires timing accuracy better than $0.5 \mu\text{s}$.
 - This equates to GOES moving of less than 300 meters.
 - Currently GOES-East moves 12000 meters per day.
 - Un-tracked movement causes increased phase noise due to hop misalignment.
 - Large hop timing misalignments will cause the demodulator to break lock.
 - Satellite movement must be tracked out before BER measurements can be made.
 - Satellite movement causes a 7 Hz shift Doppler shift in 468.8 MHz over 24 hours.

Two-Way Update – Satellite Movement

- 80 μ s travel time variation and 7 Hz frequency variation over 1 day





Two-Way Update – Satellite Movement

- Satellite Movement Solution
 - Movement is approximately sinusoidal.
 - Hand calculations are currently being performed to correct for movement.
 - Any station keeping maneuver performed by GOES will alter the hopping timing.
 - Further investigation is need to find a robust solution.



Two-Way Update – Next Steps

- Near Term
 - Complete BER measurements once power control is addressed.
 - Utilize manually predicted motion to account for time variability.
 - Prepare and submit report for this phase.
- Longer Term (depending on NOAA approval)
 - Develop automated hop alignment and tracking mechanisms.
 - Implement DCP communication protocol.
 - Demonstrate DCP control and possibly DCP feedback.